

Tate of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

Inspection Report

Supervisor SW

Minerals Regulatory Program Date of Report: May 7, 2008

Mine Name: Dry Wash
Operator Name: Miracle Rock Mining
Inspection Date: April 21, 2008
Time: 2:15-2:50 PM

Inspector(s): Paul Baker

Other Participants: A trackhoe operator named Pat was present but did not participate in the

inspection

Mine Status: Active Weather: Mostly clear, 50s,

windy

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds			
2. Public Safety (shafts, adits, trash, signs, highwalls)			
3. Protection of Drainages / Erosion Control			
4. Deleterious Material			
5. Roads (maintenance, surfacing, dust control, safety)			
6. Concurrent Reclamation			
 Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes) 			
8. Water Impoundments			
9. Soils	\boxtimes	\boxtimes	
10. Revegetation			
11. Air Quality			
12. Other		\boxtimes	

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

1. Permits, Revisions, Transfer, Bonds

On November 5, 2007, the Division approved the reclamation surety and found the Notice of Intention to Commence Small Mining Operations to be complete. The surety is for \$23,000.00.

9. Soils

The operator has been salvaging topsoil and placing it around the perimeter of the mine.

12. Other

I used a GPS unit to map the disturbed area, and it is about 2.9 acres.

Inspection Date: April 21, 2008; Report Date: May 7, 2008

S0160096

As can be seen in the photos, the operator has pulled back soil and overburden and is mining with a trackhoe.

The mine contains two areas separated by a road. The more recent disturbance is on the west side of the road. It appears the operator has pulled back a spoil pile in the area on the east side of the road although it did not appear to have been seeded.

Conclusions and Recommendations:

The operation appears to be in compliance with the rules. As areas become available, I suggest the operator do as much contemporaneous reclamation as possible, but surface preparation and seeding should be done in the fall.

Inspector's Signature

Date:

PBB:pb

cc: Dave Taylor, Miracle Rock

Attachment: GPS map



Photo 1. The active mining area.



Photo 2. This is an area where I thought it looked like overburden had been pulled back, possibly in preparation for, or as part of, reclamation.

Page 3 of 3
Inspection Date: April 21, 2008; Report Date: May 7, 2008

S0160096



Photo 3. The older pit on the east side of the road.



Photo 4. Another view of the older pit.



Photo 5. The ore within the older pit.





Photo 6. Overburden on the left, ore on the right in the newer pit.



Mine Number: \$150096


Section 24 Mine Name: DRY WASH MINE Range 10 E

Inspection Date: // Map Produced by DKS

Acres Disturbed Acres Regraded Acres Seeded Road Acres Disturbed

0000 Total Acres Distrubed Acres Released Acres Excluded Acres PreExisting Acres Prelaw

SITLA Mineral Ownership SITLA Mineral Leases **BLM Mining Notices** Inactive mines Events ... Township or range line: location doubtful



1:7,500 1 inch equals 625 feet Verify Scale Different data sources and input scales may cause misalignment of data layers. This product may not meet DOGM standards for accuracy and content.

5/8/2008 NAD 1927 UTM Zone 12N